Manf 350: Standardized Work/Takt Time

SCHOOL OF ENGINEERING

Intensive training on a manufacturing factory floor. This course will help students to improve how to observe, grasp current condition, and document. This course will introduce standardized work and takt time with focus on human movement.

3 Credits

Prerequisites

- Manf 254: Continuous Flow/Layout
- Students must be enrolled Center of Manufacturing Excellence (CME)
- Pre-Requisite: 24 Earned Hours

Instruction Type(s)

- Lecture: Lecture for Manf 350

Subject Areas

- Mechanical Engineering

The University of Mississippi is accredited by the Southern Association of Colleges and Schools Commission on Colleges to award certificates and baccalaureate, master's, specialist, and doctoral degrees. Contact the Commission on Colleges at 1866 Southern Lane, Decatur, Georgia 30033-4097, call 404-679-4500, or visit online at www.sacscoc.org for questions about the accreditation.