

# G E 504: Envi. Geochemistry Lab & Field Methods Geology & Geological Engineering

Water quality measurement and evaluation for natural, contaminated, and industrial waste water. 1 - 2 Credits

## Prerequisites

• Pre-requisite: Chem 106 or Graduate Standing

#### **Instruction Type(s)**

• Lab: Laboratory for G E 504

### **Subject Areas**

• Geology/Earth Science, General

#### **Related Areas**

- Geochemistry
- Geochemistry and Petrology
- Geological and Earth Sciences/Geosciences, Other
- Hydrology and Water Resources Science
- Paleontology